



66 Glen Cove Rd
 P.O. Box 363
 Greenvale, NY. 11548
 Tel. 516-671-3960
 Fax. 516-277-1942

www.ANZEuspension.com

PENSKE Racing Shocks & ANZE Racing Struts

Service Type	Description	qty	Price Each
SHOCK SERVICE	Complete disassembly, cleaning, inspection,	2	\$155.00
STRUT SERVICE	re-assembly with new seals, o-rings and oil.	2	\$195.00
RE-VALVE	Performed in addition to service	4	\$47.50
DYNO-MATCH	Dyno Match shock Pair	2	\$85.00
Typical Price for a set of 4			\$1,060.00

OHLINS

Service Type	Description	Price Each
SHOCK SERVICE	Complete disassembly, cleaning, inspection,	2 \$155.00
STRUT SERVICE	re-assembly with new seals, o-rings and oil.	2 \$195.00
RE-VALVE-TTX	Performed in addition to service	4 \$95.00
RE-VALVE-R&T	Performed in addition to service	4 \$47.50
DYNO-MATCH	Dyno Match shock Pair	2 \$85.00
Typical Price for a set of 4		\$1,060.00

JRZ

Service Type	Description	Price Each
SHOCK SERVICE	Complete disassembly, cleaning, inspection,	2 \$195.00
STRUT SERVICE	re-assembly with new seals, o-rings and oil.	2 \$195.00
RE-VALVE	Performed in addition to service	4 \$47.50
DYNO-MATCH	Dyno Match shock Pair	2 \$85.00
Typical Price for a set of 4		\$1,140.00

Moton

Service Type	Description	Price Each
SHOCK SERVICE	Complete disassembly, cleaning, inspection,	2 \$195.00
STRUT SERVICE	re-assembly with new seals, o-rings and oil.	2 \$195.00
RE-VALVE	Performed in addition to service	4 \$47.50
DYNO-MATCH	Dyno Match shock Pair	2 \$85.00
Typical Price for a set of 4		\$1,140.00

AST			
Service Type	Description		Price Each
SHOCK SERVICE	Complete disassembly, cleaning, inspection,	2	\$195.00
STRUT SERVICE	re-assembly with new seals, o-rings and oil.	2	\$195.00
RE-VALVE	Performed in addition to service	4	\$47.50
DYNO-MATCH	Dyno Match shock Pair	2	\$85.00
Typical Price for a set of 4			\$1,140.00

MCS			
Service Type	Description		Price Each
SHOCK SERVICE	Complete disassembly, cleaning, inspection,	2	\$195.00
STRUT SERVICE	re-assembly with new seals, o-rings and oil.	2	\$195.00
RE-VALVE	Performed in addition to service	4	\$47.50
DYNO-MATCH	Dyno Match shock Pair	2	\$85.00
Typical Price for a set of 4			\$1,140.00

Nitron			
Service Type	Description		Price Each
SHOCK SERVICE	Complete disassembly, cleaning, inspection,	2	\$195.00
STRUT SERVICE	re-assembly with new seals, o-rings and oil.	2	\$195.00
RE-VALVE	Performed in addition to service	4	\$47.50
DYNO-MATCH	Dyno Match shock Pair	2	\$85.00
Typical Price for a set of 4			\$1,140.00

Koni			
Service Type	Description		Price Each
SHOCK SERVICE	Complete disassembly, cleaning, inspection,	2	\$195.00
STRUT SERVICE	re-assembly with new seals, o-rings and oil.	2	\$195.00
RE-VALVE	Performed in addition to service	4	\$47.50
DYNO-MATCH	Dyno Match shock Pair	2	\$85.00
Typical Price for a set of 4			\$1,140.00

Service Type	Description		Price Each
REMOVE-SP-M	Remove Springs and Mounts from Dampers	4	\$25.00
EXPEDITE	Expedited Service - Per Shock	4	\$150.00
Dampers that are being rebuilt due to damage or performance issues may require additional parts such as shafts, bodies, end caps, sperical bearings, or other items.			
These items are billed on top of the standard shock or strut service price.			